



10-25-04  
10045837

corfe #

EXPRESS MAIL NO. EV331755866US  
Attorney Docket No. 95/1  
Client/Matter No. 89160.0010

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:

Mark Gurvich, Alex Rabinovich, and Jianqing He

Patent No. 6,794,954 B2

Issue Date: September 21, 2004

For: MICROSTRIP COUPLER

Certificate  
OCT 29 2004  
of Correction

CERTIFICATE OF MAILING BY EXPRESS MAIL

**ATTENTION: Certificate of Corrections Branch**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

The undersigned hereby certifies that the following documents:

1. Request for Certificate of Correction with \$100 fee;
2. Certificate of Correction (two copies);
3. Certificate of Mailing by Express Mail; and
4. Return Postcard

relating to the above application, were deposited as "Express Mail", Mailing Label No. EV331755866US with the United States Postal Service, addressed to Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on 22 October 2004

22 October 2004  
Date

10/21/04  
Date

\_\_\_\_\_  
Mailer

  
Peter J. Meza, Reg. No. 82,920  
HOGAN & HARTSON, LLP  
One Tabor Center  
1200 17th Street, Suite 1500  
Denver, Colorado 80202  
(719) 448-5906 Tel  
(303) 899-7333 Fax

OCT 29 2004



Attorney Docket No.: 95/1  
Client/Matter No: 89160.0010  
Express Mail No. EV331755866US

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

Name of Patentee:

Mark Gurvich, Alex Rabinovich, and Jianqing He

Patent No.: 6,794,954

Issued: September 21, 2004

Title: MICROSTRIP COUPLER

**ATTENTION: Certificate of Corrections Branch**

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR  
PTO MISTAKES (37 C.F.R. 1.322(a)) AND APPLICANT'S MISTAKE (37 C.F.R. 1.323)**

DEAR SIR:

Several errors appear in this patent. The errors are formatting mistakes by the PTO and Applicant. The errors occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require reexamination.

Attached hereto in duplicate is form PTO-1050, with at least one copy being suitable for printing.

10/27/2004 AWONDAF1 00000004 6794954

01 FC:1811

100.00 0P

OCT 29 2004

Please send the certificate to:

Peter J. Meza  
Hogan & Hartson LLP  
One Tabor Center  
1200 17th Street, Suite 1500  
Denver, CO 80202

The required fee of \$100 is enclosed. Any fee deficiency associated with this transmittal may be charged to Deposit Account 50-1123.

Respectfully submitted,

Date: \_\_\_\_\_

10/21/04

BY: \_\_\_\_\_



Peter J. Meza, Reg. No. 32,920  
Hogan & Hartson LLP  
One Tabor Center  
1200 17<sup>th</sup> Street, Suite 1500  
Denver, Colorado 80202  
(719) 448-5906 Tel  
(303) 899-7333 Fax

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,794,954 *B2*

DATED: September 21, 2004

INVENTOR(S): Mark Gurvich, Alex Rabinovich, and Jianqing He

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

(73) Assignee

"Power Wave Technologies, Inc." should be --Powerwave Technologies, Inc.--

(75) Inventors

"Jianqing He" should be --Jianqing He--

(57) Abstract

Line 1 "an" should be --a--

Column 2, line 25, after signal insert --.--

Column 2, line 37, after is insert --a--

Column 8, line 58, "micros trip" should be --microstrip--

Column 10, line 1, "seoarated" should be --separated--

Column 10, line 2, "outout" should be --output--

Mailing Address of Sender:  
Peter J. Meza  
Hogan & Hartson LLP  
One Tabor Center  
1200 17<sup>th</sup> Street, Suite 1500  
Denver, CO 80202

PATENT NO: 6,794,954  
No. of additional copies  
⇒ 1

Send to: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450

OCT 29 2004

# COPY

PTO/SB/44 (04-04)

Approved for use through 04/30/2007. OMB 0651-0033

Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,794,954 *B2*

DATED: September 21, 2004

INVENTOR(S): Mark Gurvich, Alex Rabinovich, and Jianqing He

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

(73) Assignee

"Power Wave Technologies, Inc." should be --Powerwave Technologies, Inc.--

(75) Inventors

"Jianquing He" should be --Jianqing He--

(57) Abstract

Line 1 "an" should be --a--

Column 2, line 25, after signal insert --.--

Column 2, line 37, after is insert --a--

Column 8, line 58, "micros trip" should be --microstrip--

Column 10, line 1, "seoarated" should be --separated--

Column 10, line 2, "outout" should be --output--

Mailing Address of Sender:

Peter J. Meza

Hogan &amp; Hartson LLP

One Tabor Center

1200 17<sup>th</sup> Street, Suite 1500

Denver, CO 80202

PATENT NO: 6,794,954

No. of additional copies

⇒ 1

Send to: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450